

表14 耐震診断結果の一覧

X 方向		加力方向 正		構造耐震判定指標 $I_{so} = E_s \cdot Z \cdot G_0 \cdot U_0 = 0.59$						診断次数第3次診断									
階	階数補正	適用式	地域指標 $Z = 1.00$		地盤指標 $G_0 = 1.00$		用途指標 $U_0 = 1.00$		経年指標 $T = 1.00$										
			F' (F_3)	$C_1 + \sum \alpha$ C_1	F_2	C_2	F_1	C_1	E_0	S_D	I_s	$C_{TU} \cdot S_D$	C_{T0}	第2種 柱本数	採用				
9F	0.40	(8)式	1.00	1.144	-	-	-	-	0.457	0.800	0.365	0.365	0.294	0	○				
			1.27	0.889	-	-	-	-	0.451		0.361	0.284	0.294	0					
			(1.50)	0.674	-	-	-	-	0.404		0.323	0.216	0.294	0					
			1.75	0.674	-	-	-	-	0.472		0.377	0.216	0.294	0					
			2.00	0.478	-	-	-	-	0.382		0.306	0.153	0.294	0					
			2.59	0.368	-	-	-	-	0.381		0.305	0.118	0.294	1					
			3.20	0.283	-	-	-	-	0.360		0.288	0.090	0.294	1					
		(7)式	1.27	0.889	-	-	1.000	0.401	0.479		0.383	0.284	0.294	0					
			(1.50)	0.674	-	-	1.000	0.616	0.473		0.378	0.216	0.294	0					
			1.75	0.674	-	-	1.000	0.616	0.532		0.425	0.216	0.294	0					
			2.00	0.478	-	-	1.000	0.756	0.487		0.390	0.153	0.294	0					
			2.59	0.368	-	-	1.000	0.836	0.507		0.405	0.118	0.294	1					
			3.20	0.283	1.750	0.393	1.000	0.616	0.515		0.412	0.090	0.294	1					
			8F	0.51	(8)式	1.00	0.729	-	-		-	-	0.375	1.000	0.375	0.375	0.245	0	
1.27	0.616	-				-	-	-	0.402	0.402	0.317	0.245	0						
(1.50)	0.373	-				-	-	-	0.289	0.289	0.192	0.245	0						
2.00	0.373	-				-	-	-	0.385	0.385	0.192	0.245	0						
3.00	0.326	-				-	-	-	0.503	0.503	0.168	0.245	0						
3.50	0.249	-				-	-	-	0.447	0.447	0.128	0.245	0						
(7)式	1.27	0.616				-	-	1.000	0.183	0.413	0.413	0.317	0.245		0	○			
	(1.50)	0.373			-	-	1.000	0.426	0.362	0.362	0.192	0.245	0						
	2.00	0.373			-	-	1.000	0.426	0.443	0.443	0.192	0.245	0						
	3.00	0.326			-	-	1.000	0.468	0.557	0.557	0.168	0.245	0						
	3.50	0.249			-	-	1.000	0.530	0.524	0.524	0.128	0.245	0						
	7F	0.590			(8)式	1.27	0.665	-	-	-	-	0.497	1.000		0.497	0.392	0.245	0	○
						(1.50)	0.432	-	-	-	-	0.382			0.382	0.255	0.245	0	
2.00						0.432	-	-	-	-	0.509	0.509			0.255	0.245	0		
3.20			0.417	-		-	-	-	0.788	0.788	0.246	0.245		0					
3.50			0.314	-		-	-	-	0.647	0.647	0.185	0.245		0					
(7)式			(1.50)	0.432		-	-	1.270	0.232	0.420	0.420	0.255		0.245	0				
			2.00	0.432		-	-	1.270	0.232	0.538	0.538	0.255		0.245	0				
			3.20	0.417	-	-	1.270	0.246	0.809	0.809	0.246	0.245		0					
			3.50	0.314	3.200	0.103	1.270	0.246	0.701	0.701	0.185	0.245		0					
			6F	0.652	(8)式	1.27	0.639	-	-	-	-	0.530		1.000	0.530	0.417	0.245	0	○
						(1.50)	0.411	-	-	-	-	0.402			0.402	0.268	0.245	0	
						2.50	0.411	-	-	-	-	0.670			0.670	0.268	0.245	0	
診断者コメント																			

表14 耐震診断結果の一覧

X 方向		加力方向 正		構造耐震判定指標 $I_{so} = E_s \cdot Z \cdot G_0 \cdot U_0 = 0.59$						経年指標 $T = 1.00$					
診断次数第3次診断		地域指標 $Z = 1.00$		地盤指標 $G_0 = 1.00$		用途指標 $U_0 = 1.00$		経年指標 $T = 1.00$							
階	階数補正	適用式	F' (F_3)	$C_1 + \sum \alpha$ C_1	F_2	C_2	F_1	C_1	E_0	S_D	I_s	$C_{TU} \cdot S_D$	C_{T0}	第2種 柱本数	採用
6F	0.65	(8)式	2.59	0.311	-	-	-	-	0.527	1.000	0.527	0.203	0.245	0	
			3.50	0.238	-	-	-	-	0.542		0.542	0.155	0.245	0	
			(1.50)	0.411	-	-	1.270	0.228	0.444		0.444	0.268	0.245	0	
		(7)式	2.50	0.411	-	-	1.270	0.228	0.696		0.696	0.268	0.245	0	
			2.59	0.311	-	-	1.270	0.328	0.593		0.593	0.203	0.245	0	
			3.50	0.238	2.500	0.173	1.270	0.228	0.640		0.640	0.155	0.245	0	
5F	0.71	(8)式	1.27	0.554	-	-	-	-	0.499	1.000	0.499	0.393	0.245	0	○
			(1.50)	0.351	-	-	-	-	0.374		0.374	0.249	0.245	0	
			2.00	0.351	-	-	-	-	0.498		0.498	0.249	0.245	0	
			2.50	0.330	-	-	-	-	0.584		0.584	0.234	0.245	0	
			2.59	0.247	-	-	-	-	0.454		0.454	0.175	0.245	0	
			3.00	0.185	-	-	-	-	0.394		0.394	0.131	0.245	0	
		(7)式	3.50	0.118	-	-	-	-	0.292		0.292	0.084	0.245	0	
			(1.50)	0.351	-	-	1.270	0.203	0.416		0.416	0.249	0.245	0	
			2.00	0.351	-	-	1.270	0.203	0.531		0.531	0.249	0.245	0	
			2.50	0.330	-	-	1.270	0.226	0.618		0.618	0.234	0.245	0	
			2.59	0.247	-	-	1.270	0.307	0.532		0.532	0.175	0.245	0	
			3.00	0.185	-	-	1.270	0.369	0.515		0.515	0.131	0.245	0	
4F	0.773	(8)式	1.27	1.188	-	-	-	-	1.166	1.000	1.166	0.918	0.245	0	○
			(1.50)	0.087	-	-	-	-	0.101		0.101	0.067	0.245	0	
			2.59	0.087	-	-	-	-	0.175		0.175	0.067	0.245	0	
		(7)式	3.50	0.052	-	-	-	-	0.140		0.140	0.040	0.245	0	
			(1.50)	0.087	-	-	1.270	1.100	1.085		1.085	0.067	0.245	0	
			2.59	0.087	-	-	1.270	1.100	1.094		1.094	0.067	0.245	0	
3F	0.841	(8)式	1.27	0.650	-	-	-	-	0.695	0.800	0.556	0.438	0.245	0	○
			(1.50)	0.218	-	-	-	-	0.274		0.220	0.146	0.245	0	
			2.59	0.218	-	-	-	-	0.474		0.379	0.146	0.245	0	
		(7)式	3.00	0.195	-	-	-	-	0.492		0.394	0.131	0.245	0	
			3.20	0.174	-	-	-	-	0.467		0.374	0.117	0.245	0	
			3.50	0.094	-	-	-	-	0.277		0.221	0.063	0.245	0	
診断者コメント															

表14 耐震診断結果の一覧

X 方向		加力方向 正		構造耐震判定指標 $I_{so} = E_s \cdot Z \cdot G_0 \cdot U_0 = 0.59$								経年指標 $T = 1.00$			
診断次数第3次診断		地域指標 $Z = 1.00$		地盤指標 $G_0 = 1.00$		用途指標 $U_0 = 1.00$				経年指標 $T = 1.00$					
階	階数補正	適用式	F' (F_3)	$C_1 + \sum \alpha$ C_1	F_2	C_2	F_1	C_1	E_0	S_D	I_s	$C_{TU} \cdot S_D$	C_{T0}	第2種 柱本数	採用
3F	0.84	(7)式	3.50	0.094	-	-	1.270	0.556	0.656	0.800	0.525	0.063	0.245	0	
2F	0.91	(8)式	1.27	0.784	-	-	-	-	0.908	0.900	0.817	0.643	0.245	0	○
			(1.50)	0.142	-	-	-	-	0.195		0.176	0.117	0.245	0	
			3.00	0.142	-	-	-	-	0.391		0.351	0.117	0.245	0	
		(7)式	3.50	0.118	-	-	-	-	0.377		0.339	0.097	0.245	0	
			(1.50)	0.142	-	-	1.270	0.641	0.768		0.691	0.117	0.245	0	
			3.00	0.142	-	-	1.270	0.641	0.839		0.755	0.117	0.245	0	
1F	1.00	(8)式	3.50	0.118	-	-	1.270	0.665	0.858	0.772	0.097	0.245	0		
			1.00	0.555	-	-	-	-	0.555	0.810	0.450	0.450	0.245	0	
			1.27	0.771	-	-	-	-	0.979		0.793	0.625	0.245	0	
			1.50	0.101	-	-	-	-	0.152		0.123	0.082	0.245	0	
			2.00	0.100	-	-	-	-	0.201		0.162	0.081	0.245	0	
		3.20	0.095	-	-	-	-	0.304	0.246		0.077	0.245	0		
		(7)式	3.50	0.068	-	-	-	-	0.239		0.194	0.055	0.245	0	
			1.27	0.771	-	-	1.000	0.002	0.979		0.793	0.625	0.245	0	○
			1.50	0.101	1.270	0.670	1.000	0.002	0.864		0.700	0.082	0.245	0	
			2.00	0.100	1.270	0.671	1.000	0.002	0.875		0.709	0.081	0.245	0	
3.20	0.095		1.270	0.676	1.000	0.002	0.911	0.738	0.077		0.245	0			
3.50	0.068	1.270	0.703	1.000	0.002	0.924	0.748	0.055	0.245	0					
診断者コメント															